

# PathStone Group




PathStoneGroup.com



## STATISTICAL PROCESS CONTROL

# Agenda

1. SPC: What is it ?
2. SPC purpose and benefits
3. Control Chart
4. SPC Analysis
5. Types of Data
6. Takeaways




# Introduction

## What is it ?

**Statistical Process Control (SPC)** is a method of measuring and **controlling** quality by **monitoring** the manufacturing process.

SPC refers to a scientific, **data-driven method** for quality **analysis** and **improvement** that allows us to prevent problems from occurring.

The **process data** that is collected in **Control Charts** and is used to evaluate, monitor and control it.



"Without data, you're just another person with an opinion."

**Edwards Deming**

# Introduction

## Purpose and Benefits

One of the advantages of SPC is the ability to use it for **analysis through control charts**.

SPC is an effective method to drive **continuous improvement**.

SPC can **predict** processes performance, help to take **better decisions**, find **correlations** with process variables and implement solid **quality management**.



## Control Chart


A **control chart** is a smart line graph. It performs calculations on the data and displays the average or median as a center line and the amount of variation in data using **control limit lines**.

As data moves through the zones created by these control limits, a control chart highlights data points or trends that should be investigated:

- An **Upper Control Limit** (UCL) line calculated at 3 sigma above the Center Line.
- A line chart of data measuring the process over time.
- A **Center Line** calculated as the average or median of the data.
- A **Lower Control Limit** (LCL) line calculated at 3 sigma below the Center Line.

# SPC

## Control Chart



## Control Chart

The **average (mean)** is used for the centerline (instead of the median, used on a run chart). **Control limits** are added, representing the range of expected variation. The control limits are approximately  $\pm 3$  standard deviations off the average (99.7% of the points in a set of normally distributed data will fall between the limits).

Control limits **are not specification** limits. Control limits are based on data and tell us how a process is performing. Spec limits are based on customer requirements and tell us how we want a process to perform.

## SPC Analysis

We use quality and process control procedures in production and service processes to ensure that the products or services **continue to meet the specifications**.


With a control chart **will be clear to see** where the two changes were made in the process, each of which resulted in a reduction of the variation in the process.

When the operator or team leader in the process uses this type of graph, it can be **deduced whether the process is still stable**. When a value moves within the limits, the process is under control.



# SPC

## The 7 types of Control Charts and the Normal Distribution Chart.



"Adjusted" Normal Distribution

Normal Distribution

Binomial Distribution:  
Only "Y / N" possible outcomes


Poisson Distribution:  
Probability of outcome in a defined interval

	1st Chart	Average of Subgroup Averages	Average of Subgroup Averages	Average of Subgroup Averages	Average of Subgroup Averages
Individual Average of data points	$\bar{X}$	$\bar{\bar{X}}$	$\bar{\bar{X}}$	$\bar{\bar{X}}$	$\bar{\bar{X}}$
2nd Chart	Moving range of data points	Average of Subgroup Ranges	Average of Subgroup Standard Deviation	Average of Subgroup Standard Deviation	Average of Subgroup Standard Deviation
	$mR$	$\bar{R}$	$\bar{S}$	$\bar{S}$	$\bar{S}$

Average of Subgroup Averages	Average of Subgroup Averages	Average of Subgroup Averages	Average of Subgroup Averages
$\bar{np}$	$\bar{p}$	$\bar{c}$	$\bar{u}$
None	None	None	None

$\bar{\bar{X}}$  = Mean of the means or "Grand mean"

# SPC




## Types of data

### Continuous

Any variable measured on a continuum or scale that can be infinitely divided. There are more powerful statistical tools for interpreting continuous data, so it is preferred over discrete/attribute data.

Example:

Lead time, cost or price, duration of call, and any physical dimensions or characteristics (height, weight, density, temperature).



# SPC

## Types of data

### Discrete (also called Attribute)


**Count:** Example, counts of errors.

**Binary data:** Data that can have only one of two values.

Example:

On-time delivery (yes/no); Acceptable product (pass/fail).

### ATTRIBUTE DATA



errors      defects      pass no-pass      go no-go

**ALWAYS CONTAINS WHOLE NUMBERS**

COUNT DEFECTS	Constant sample	<b>u chart</b>
	Variable sample	<b>c chart</b>
COUNT DEFECTIVES	Constant sample	<b>p chart</b>
	Variable sample	<b>np chart</b>

**A defective unit may contain more than One defect**

# SPC

## Types of data

### Discrete (also called Attribute)


**Attribute–Nominal:** The “data” are names or labels. There is no intrinsic reason to arrange in any order or make a statement about any quantitative differences between them.

Example:

In a company: Dept A, Dept B, Dept C

In a shop: Machine 1, Machine 2, Machine 3

Types of transport: boat, train, plane



# SPC

## Types of data

### Discrete (also called Attribute)


**Attribute–Ordinal:** The names or labels represent some value inherent in the object or item (so there is an obvious order to the labels).

Example:

**On product performance:** excellent, very good, good, fair, poor

**Salsa taste test:** mild, hot, very hot, makes me suffer

**Customer survey:** strongly agree, agree, disagree, strongly disagree




# SPC

## Types of data

The data points recorded on a control chart should fall between the control limits, provided that only **common causes** and no special causes have been identified.

Common causes will fall between the control limits, whereas **special causes** are **outliers** or are outside of the control limits.




# SPC

## Types of data

Some examples of **common cause** variation are:

- Variation in material properties within specification.
- Seasonal changes in ambient temperature or humidity.
- Normal machine or tooling wear.
- Variability in operator-controlled settings.
- Normal measurement variation.






## Types of data

Some examples of **special cause** variation are below:

- Failed controllers.
- Improper equipment adjustments.
- A change in the measurement system.
- A process shift.
- Machine malfunction.
- Raw material properties out of design specifications.
- Broken tool, punch, bit, etc.
- Inexperienced operator not familiar with process.




# SPC

## Types of data


By addressing any **special causes**, trends or shifts in the process, we can assure we are producing parts that **meet the customer's requirements**.

The control limits should **always fall between the spec limits** determined by the process experts and / or the customer.




# SPC

With current computer technology, there are several affordable software and MS Excel® add-ins to calculate and graph control charts without the need to learn complex formulas. Using templates is more practical in real-life operations.





# LEGO Defect Process Control



**LEARNING HUB**



Lego Defect Process Control



# Control Chart Template



# Takeaways

- Remember that without data, all we have is **opinions and “gut-feelings”**, and they won’t help us to solve most complex problems.
- **Reduce special cause variation** by tracking down and eliminating the specific, assignable root cause(s), looking for “what is different” in the process when the special cause variation appears.
- **Understand well the SPC foundations** and let a **SPC software** application do the heavy lifting. There are many affordable software out there, many as MS Excel add-ons.



Thank You



# PathStone Group



PathStoneGroup.com

## Copyright notice -

This content is copyright of © PathStone Group 2022. All rights reserved.

Any redistribution or reproduction of part or all of the contents in any form is prohibited other than the following:

- you may print or download to a local hard disk extracts for your personal and non-commercial use only
- you may copy the content to individual third parties for their personal use, but only if you acknowledge the PathStone Group website as the source of the material

You may not, except with our express written permission, distribute or commercially exploit the content. Nor may you transmit it or store it in any other website or other form of electronic retrieval system.

# STATISTICAL PROCESS CONTROL





# PathStone Group



PathStoneGroup.com



Get the Book



Page: 282

[edgar@pathstonegroup.com](mailto:edgar@pathstonegroup.com)

**Reference:** Focused Excellence  
by Edgar Anaya  
© 2022

A Practical Tool Book for  
**Business Competitiveness and  
Lean Transformation**